

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 1946

Date Inspected Aug 25, 1923

If so how and location from
first manhole down stream

House No. Lot 9B 2975
2137

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 inch

239 feet from West Main Hole 7 foot deep.

Was lateral at curb? yes


Name of Contractor

Was attached to main yes

Julius Wittman

Show by diagram relation of lateral to wall of building served.

18 inches from North
West corner the building
5 foot deep.



Signed

Wm. Dickson

Inspector for City

Filed at Engineer's Office

8/27/23

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1946

PERMIT TO TAP SEWER

Massillon, O.,

19

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot No. St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor