

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3-10

Nº 1951

Date Inspected Sept 2, 1925

If so how and location from
first manhole down stream

House No. Lat No. 3563, 402

Size of pipe used 4 inch

Distance from first manhole
down stream to ditch at
curb line and depth

12.4 feet from Man. Hole West 6-8 deep

Was lateral at curb? yes


Name of Contractor

Chas. Stout

Was attached to main yes

Show by diagram relation of lateral to wall of building served.

5. feet from the
north West corner
the porch.
6.4 Bafe.



Signed

Mr. Dushon
Inspector for City

Filed at Engineer's Office

Sept 4, 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1951

PERMIT TO TAP SEWER

Massillon, O.,

Aug 26th 1925

Received of

Chas H. ... fee of \$ 2.00

for which permission is granted

to tap

Laurel ... sewer, on the

South side

of

Kramer ... Ave., the premises being Lot. No. 3513
St. 7026

House No. 339

Work to be done in accordance with Ordinance No. 2323, duly passed
by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Chas H. ...