

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 1952

Date Inspected Sept 5, 1925

House No. 1721 1/2 7668

Size of pipe used 6 inch

Was lateral at curb? yes

Was attached to main yes.


Show by diagram relation of lateral to wall of building served.

12 inches from North
West corner Main
Building
6-6 Deep.

If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth 47. feet from Main. Hole. 4. feet Deep.

Name of Contractor Jesse Brunkner & John Deshon



Signed Wm. Deshon
Inspector for City

Filed at Engineer's Office

SEP 9 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1952

PERMIT TO TAP SEWER

Massillon, O.,

August 27th 1925

Received of

Jess Brunken

fee of \$

2.00

for which permission is granted

James & Mary H. Quinn

to tap

Sanitary

sewer, on the

South

side

of

Entle

Ave., the premises being Lot. No.

269

St.

7668

House No.

721349

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

J. Brunken