

N^o 1953

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED



Date Inspected Aug. 31, 1925

If so how and location from
first manhole down stream

House No. Lot. No. 35-23-40

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 4 inch

245 feet from Main Hole south 7.6 ft deep

Was lateral at curb? yes


Was attached to main yes

Name of Contractor

James Brunken & John Carlson

Show by diagram relation of lateral to wall of building served.

12 inches from south
East corner Main
Building
7 foot deep.



Signed

Wm. Heslow

Inspector for City

Filed at Engineer's Office

Sept 1st 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1953

PERMIT TO TAP SEWER

Massillon, O.,

Aug 28th 1925

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

St.

House No. 1026

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor