

Nº 1954

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

~~NO RECORD~~

✓
D

11/15

Date Inspected Sept. 3, 1925

If so how and location from
first manhole down stream

House No. 1713. Lot No. 3742

Distance from first manhole

Size of pipe used 4 inch

down stream to ditch at
curb line and depth

12.3 from Man Hole. Depth 5 feet deep.

Was lateral at curb? yes


Name of Contractor

John Rist

Was attached to main yes.

Show by diagram relation of lateral to wall of building served.

5-6 from south
east corner the
porch.
4 foot deep



Signed

Wm. Nesbitt
Inspector for City

Filed at Engineer's Office

Sept 4th 1925

Remarks

~~No Record~~

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1954

PERMIT TO TAP SEWER

Massillon, O., Aug 29th 1925

Received of R. Heberling fee of \$ 2.00

for which permission is granted West

to tap Sanitary sewer, on the West side

of China 11th ST NE Ave., the premises being Lot. No. 2242
St. 7402

House No. 1045
1313 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor West