

✓

D

3-11

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No 1959

Date Inspected Sept. 12, 1925

House No. 1717-1323

Size of pipe used 6 inch

Was lateral at curb? yes

Was attached to main _____


Show by diagram relation of lateral to wall of building served.

If so how and location from
first manhole down stream _____

Distance from first manhole
down stream to ditch at
curb line and depth 149 feet from Manhole south 7-6. Depth

Name of Contractor Jesse Brunker & John Desbore

going in south east
corner the Main Building
7.00 feet Deep



Signed _____

John Desbore

Inspector for City

Filed at Engineer's Office _____

SEP 18 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1959

PERMIT TO TAP SEWER

Massillon, O.,

Sept 1st 1925

Received of

J. B. Bunker

fee of \$

2.00

for which permission is granted

W. L. Bunker

to tap

Sanitary

sewer, on the

West
2542

side

of

1/2 mile

1st ST NE

Ave., the premises being Lot. No.

1195

House No.

1323
1919

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rules of the Department of Public Service.

Name of Contractor

J. B. Bunker