

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 1967

LOT "10088"

Date Inspected Sept 8, 1925

If so how and location from
first manhole down stream

House No. 1504, 1808

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 inch

22-4 from Man Hole East 7-4 Deep.

Was lateral at curb? yes


Name of Contractor

A. Cuper

Was attached to main yes

Show by diagram relation of lateral to wall of building served.

2-6. from South
West corner the
Main Building
6.0 Deep.



Signed

Wm. Deshon

Inspector for City

Filed at Engineer's Office

SEP 9 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1967

PERMIT TO TAP SEWER

Massillon, O.,

Sept 8

19 *25*

Received of

A + E Rehr

fee of \$

2.00

for which permission is granted

to tap

Sanitary

sewer, on the

West East

side

of

George St.

Ave., the premises being Lot No.

10088

78

House No.

808

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

A Cupio