## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

5-6

]	Date Inspected Defall 12,199	If so how and location from
. 7	II.	first manhole down stream
	House No.	Distance from first manhole
,	Size of pipe used for the	down stream to ditch at curb line and depth 105 feet from Mole Louds 5-7.6
. 1	Was lateral at curb? MAN.	
	Was attached to main	Name of Contractor Justine Illinoun
(	Show by diagram relation of lateral to	wall of building served.
	1-6 from No Borner The 5 feet Deep	all grant
	Corner Mil	2 / Gredeny
	5 feet Deep	0.
	OA = IO	1 culty
Ş	Signed	Filed at Engineer's Office SEP 1 8 1925
	Inspector for City	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 1974

## PERMIT TO TAP SEWER

			11 1	A .
		Massillon, O.,	Sept 1	6 th 1925
Received of	Julio 11	Atman	fee of \$	200
for which permission	C Chi	Osler	William State Conf.	
to tap La	itany U	_sewer, on the	Wast	side
of M	Mill 1st ST NE		ses being Lot. No.	3
100   House No. 156		St.	Ordinance No. 23	23 duly passed
	, and Rules of the Depa			o, dary passen
Name of Contractor	AD 1	Thuran	garage en	