

Nº 1976

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Date Inspected Sept. 19, 1925

House No. _____

Size of pipe used 4 inch

Was lateral at curb? Yes

Was attached to main yes


Show by diagram relation of lateral to wall of building served.

18. inches from Bath east
porch pillar.
4-8. Deep.

If so how and location from first manhole down stream 121-5. from Man Hole south 2 feet deep

Distance from first manhole down stream to ditch at curb line and depth 128-4. from Man Hole south 22 inches deep

Name of Contractor Chas. Street



Signed _____

Wm. D. Shaw
Inspector for City

curb
Filed at Engineer's Office

SEP 21 1925

Remarks _____

Can't locate by
lot no. or house no.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1976

PERMIT TO TAP SEWER

Massillon, O.,

Sept 17th 1925

Received of

Chas. Stroud

fee of \$ 2⁰⁰

for which permission is granted

Linde & Harsh

to tap

Sanitary

sewer, on the

West

side

of

6th

Ave., the premises being Lot. No.

St.

House No. Work to be done in accordance with Ordinance No. 2323, duly passed
by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Chas. Stroud