

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 1981

✓
D

Date Inspected Sept 21, 1925

If so how and location from first manhole down stream 6 4 feet from Man. Holes south 2-3. Deep

House No. port lot 151

Distance from first manhole down stream to ditch at curb line and depth 61-0. from Man. Holes south 2-0. Deep

Size of pipe used 4 inch


Was lateral at curb? 98

Name of Contractor Chas. Strout

Was attached to main yes

Show by diagram relation of lateral to wall of building served.

3-6 from south West
Corner the porch.
6-0. Deep.



Signed Mr. Dishon
Inspector for City

Filed at Engineer's Office

SEP 23 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1981

PERMIT TO TAP SEWER

Massillon, O.,

1986

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

10th ST NE

Ave., the premises being Lot. No. St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor