

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED


Nº 1986

LOT 9605

Date Inspected Sept 25 1925 If so how and location from
first manhole down stream _____
House No. Lot 9605 152 Distance from first manhole
down stream to ditch at
Size of pipe used 6 inch curb line and depth 112-3 from Manhole south 3-6 Deep
Was lateral at curb? yes Name of Contractor John Vist
Was attached to main _____

Show by diagram relation of lateral to wall of building served.

8-2. from South West
corner the porch.
7-2. Deep



Signed _____

Inspector for City

Filed at Engineer's Office

Sept 26th 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 1986

PERMIT TO TAP SEWER

Massillon, O.,

Sept 24 1925

Received of

fee of \$

2.00

for which permission is granted

to tap

sewer, on the

side

of

St.

Ave., the premises being Lot. No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Nist

SR 3/31