


FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No 1988

Date Inspected Sept. 29, 1925 If so how and location from
first manhole down stream _____
House No. 1519614 Distance from first manhole
down stream to ditch at
Size of pipe used 6 inches curb line and depth 129 - 10. from Man. Hole South. 3 - 6. Deep.
Was lateral at curb? yes. Name of Contractor James Krumpholtz & John L. Smith
Was attached to main _____

Show by diagram relation of lateral to wall of building served.

4.00. feet from South West
corner the porch pillars
6 - 2. Deep.



Signed _____

Mr. Dushan

Inspector for City

Filed at Engineer's Office

OCT 1 - 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 1988

PERMIT TO TAP SEWER

Massillon, O.,

Sept. 78 1978

Received of

Jess Brunner

fee of \$

2.00

for which permission is granted

Otto Buhmaier

to tap

Sanitary

sewer, on the

east

side

of

Fruit

Seneca

Ave., the premises being Lot. No.

9614 151

St.

House No.

860

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Brunner & Seaton