

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 1989

Date Inspected Oct 1, 1925

If so how and location from
first manhole down stream

House No. Lot 93. 4017717

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in.

119-00. from Main Hole. Path 8-0. Depth

Was lateral at curb? yes


Name of Contractor

Was attached to main

James Brunner & John DeLeon

Show by diagram relation of lateral to wall of building served.

4-4. from South
East corner the
Ranch.
8-0. Path Depth.



Signed

John DeLeon
Inspector for City

Filed at Engineer's Office

OCT 1 - 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No 1989

Massillon, O., Sept 28, 192

Received of Jess Brunken fee of \$ 2.00

for which permission is granted Wm Schneider

to tap sanitary sewer, on the west side
of 324 Washington St. Ave., the premises being Lot. No. 401
7717

House No. 1041. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Brunken & Deaton