FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

Nº 1990	AND SIGNED WHEN RETURNED
arros gar jörd	
Date Inspected NOV. 24-1925	If so how and location from first manhole down stream
House No. 822626 Size of pipe used 6 FROM CUPB TO WALL BAL'. 4"	Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb? YES	Name of Contractor JULIUS WITTMANN.
Was attached to main	
Show by diagram relation of lateral to	wall of building served. House
44 S	6 PIPE 1 PIPE.
	CORB. HOUSE.
Signed Fred. C. Dearway Inspector for City	Filed at Engineer's Office NOV 2 4 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER 1990

	n and comment of agen	Massillon, O.,	Apr 29th	19_3 \$
Pagaived of	Julins	Wittn ann	fee of \$, 00
for which permiss	ion is granted	Jaggers		
	1.	sewer, on the	Cark	side
to tap	clay		nises being Lot. No.	2041
01		St.	3531	

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor