## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 1991

all the same	e de la frence de la companya de la	
Date Inspected Vell 30.1725	If so how and location from first manhole down stream 23-6 from Man Notes fact I	10-4.6-01
House No. Lat 1900	Distance from first manhole	( × 1
Size of pipe used 6 mills	down stream to ditch at curb line and depth 50-les from More More Month of	outles-61
Was lateral at curb?	Name of Contractor Onas - Mouto	
Was attached to main 46	ivalife of Collifactor	
Show by diagram relation of lateral to	wall of building served.	
10.000 Jugar april		
West evener	me and the second	
The Millian		·
5+00 fort Dupl		
and and and	Edward E euch	
Signed Im. Ne	Filed at Engineer's Office 1631-19	25
Inspector for Cit		
Remarks		

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## **Nº** 1991

## PERMIT TO TAP SEWER

-		Massillor	ı, O.,	y 1 30 m	19.2.5
Received of	Chas	Strond	H	fee of \$ $\mathcal{Z}$	00
or wh <b>ich permi</b> ssion	4	e the	Leily		
o tap Sa	itang	sewer, on the	21	esh	side
of and	then	<del>Avc</del> ., the St.	premises being	g Lot. No. 15	00
House No.		e done in accordanc	e with Ordinar	ice No. 2323, du	ly passed
er i		Department of Pub			
Sally Contractor	tha St	- und			