

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 1993

Date Inspected Oct 1, 1925

If so how and location from
first manhole down stream _____

House No. 419.328

Distance from first manhole
down stream to ditch at
curb line and depth _____

Size of pipe used 6 inch

24-5. ft. Man Hole Both 4-10. ft. deep

Was lateral at curb? yes.



Name of Contractor _____

Jesse Brunkner to John Deshou

Was attached to main _____

Show by diagram relation of lateral to wall of building served.

*Plat should be turned
over.
Doc. Sherzger saw Mr. Trotter
+ he said lateral came in on
lot # 2569
Mar 15 1935*



Signed _____

Inspector for City

Filed at Engineer's Office

OCT 1 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1993

PERMIT TO TAP SEWER

Massillon, O., Oct 1 1923

Received of

Robert Trotter

fee of \$

2⁰⁰

for which permission is granted

Robert Trotter

to tap

Seam

sewer, on the

East

side

of

Clay

Ave., the premises being Lot. No.

EO69

1209
170

St.

House No.

776

328 (New)

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Brunkner Decker

5/10
5/10