

No 1994

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

5

Date Inspected Oct 5, 1925

If so how and location from
first manhole down stream

House No. 102 Lot 3 554

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 inch

6-0. feet from Manhole East. 4-0. Depth


Was lateral at curb? Yes

Name of Contractor Mr. Limbach

Was attached to main

Show by diagram relation of lateral to wall of building served.

7-6. from South East
corner the Building
4-0. feet. Depth



Signed

Wm. Desbrow

Inspector for City

Filed at Engineer's Office

OCT 6 - 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1994

PERMIT TO TAP SEWER

Massillon, O., Oct 1 1925

Received of Mr. Lumbard fee of \$ 2.00

for which permission is granted Mr. Kosowski

to tap Sanitary sewer, on the South side

of Grange Ave., the premises being Lot. No. 101
GROUSE St. 3554

House No. 103 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Mr. Lumbard

5 R. 5/3