

Nº 1995

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Date Inspected Oct 3, 1925

If so how and location from
first manhole down stream

House No. 1219 9514 3439

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 inch


Was lateral at curb? yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

6-6. from Bath
that corner the
Building
7-0 Deep



Signed

Inspector for City

Filed at Engineer's Office

OCT 6 - 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1995

PERMIT TO TAP SEWER

Massillon, O., Sept 2 - 192

Received of Brunker & Deshon fee of \$ 2.00

for which permission is granted Fred Zorger

to tap Sanitary sewer, on the South side

of Bluff Ave., the premises being Lot. No. 5517
St. 3439

House No. 1 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Brunker & Deshon

SR. 5/7
27

per

28