## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 1997

Date Inspected 18t 2:19R3	If so how and location from first manhole down stream
House No. 23 Size of pipe used 4 100 Size	Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb?	Name of Contractor
Show by diagram relation of lateral to	wall of building served.
23. fik fr Yout the factor the f 3-6. Delp	Building
SignedInspector for Ci	Filed at Engineer's Office OCT 1925

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

**Nº** 1997

## PERMIT TO TAP SEWER

	Massillon, O., Och 2 and 1925
Received of Chas Str	fee of \$ 2
for which permission is granted	$\Lambda$
to tap sewer	faller of the beautiful of the second
of E Walnut	Ave., the premises being Lot. No.
House No. Work to be done in ac	cordance with Ordinance No. 2323, duly passed
by the City Council, and Rules of the Department	of Public Service.
Name of Contractor Clas Struck	