



FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No 2000

Date Inspected Oct. 8, 1925

House No. Lot 13, 200

Size of pipe used 6 inch

Was lateral at curb? _____

Was attached to main yes

Show by diagram relation of lateral to wall of building served.


12-0. from the
South east corner
the Building
11-0. Dup

If so how and location from first manhole down stream 104-4. from West curb line

Distance from first manhole down stream to ditch at curb line and depth of Houston St.

Name of Contractor Chas. Trout

12-0. from the
South east corner
the Building
11-0. Dup



Signed John. Westover
Inspector for City

Filed at Engineer's Office 10/14/25

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2000

PERMIT TO TAP SEWER

Massillon, O., 10/7/25 19

Received of Chas Strand fee of \$ 2.00

for which permission is granted Finerock Furniture Co.

to tap Sanitary sewer, on the south side

of Main Ave., the premises being Lot. No. 200
St.

House No. 1101 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Chas Strand