

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2001

3-36

Date Inspected Oct.

If so how and location from
first manhole down stream _____

House No. Lot B. 297A

Distance from first manhole
down stream to ditch at
curb line and depth 75-10. from Man Hole gate 4-0. Pipe.

Size of pipe used 6 inch


Was lateral at curb? yes

Name of Contractor James Brunner & John Desbrow

Was attached to main _____

Show by diagram relation of lateral to wall of building served.

3-0. from North West
corner from the
porch pillar



Signed _____

Am. Desbrow
Inspector for City

Filed at Engineer's Office

10/14/25

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2001

PERMIT TO TAP SEWER

Massillon, O., Oct 8 1920

Received of Arthur B. Bunker fee of \$ 2.00

for which permission is granted Harry Johnson

to tap Sanitary sewer, on the ~~West~~ South side

of M. Main Ave., the premises being Lot. No. 4541
St. 297-1

House No. 1507. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Arthur B. Bunker