Nº 2003

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

MAD INDIA	
Date Inspected 18/12.13.27	If so how and location from first manhole down stream 42-6. Law About Man Sala 1881 6.6.
House No. 130 7. 911	Distance from first manhole
Size of pipe used 6 1200	down stream to ditch at curb line and depth
Was lateral at curb?	Name of Contractor Im July
Was attached to main	Name of Contractor
Show by diagram relation of lateral to	wall of building served.
2-0. fet from & Part Color	outh & Jewel.
6 Buldon	
7-0. Duf	
Signed Im De	show Filed at Engineer's Office 10/14/25
Inspector for Cit	
Remarks	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2003 PERMIT TO TAP SEWER

Received of	
o tap Sanday sewer, on the Mes	
	Lsid
8th ST SW Ave., the premises being Lot. I	To. 3281 '
ouse No. 1307. Work to be done in accordance with Ordinance No.	2323, duly passe