AND SIGNED WHEN RETURNED

4-6

Date Inspected Dat 14,1925	If so how and location from first manhole down stream
Size of pipe used (mel)	Distance from first manhole down stream to ditch at curb line and depth 91-0. from Man Hole West 11-0. Deep
Was lateral at curb? Ms attached to main	Name of Contractor Chas. Street
Show by diagram relation of lateral to 2-10: from Mrs. 2-10: from Mrs. 7-0: fut	wall of building served. The fast reh Pullat
	C. Current
Signed Inspector for Ci	Filed at Engineer's Office 10/14/25
Remarks	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2004

PERMIT TO TAP SEWER

		Massillon,	o.,	cl 9t	19 23
		772			00
Received of		Salar Called	The state of	fee of \$	2
Tanan ing pangganan kananan sa pangganan sa pangganan sa pangganan sa pangganan sa pangganan sa pangganan sa p	$\mathcal{O}(\mathcal{O})$	1 02	A.		
or which permission	on is granted	Marie Marie Manuel Marie	Carried Mary San Marie San		
o tap	anting	sewer, on the	L	-A.	side
The second secon					
\sim \sim	As.	Ave., the p	oremises being	z Lot No	1053
809		St.	or consider the same	5 200 110	
House No. 130	7 Work to be	done in accordance	with Ordinan	ice No. 2323,	duly passed
by the City Counci	l, and Rules of the D	epartment of Public	Service.		
Name of Contracto	or Chas St	tred			