

Nº 2008

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

4-14

Date Inspected Oct 15, 1925

If so how and location from
first manhole down stream

House No. Lot 42. 1462.

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 inch

40-0. from Man Hole to 6-0. depth

Was lateral at curb? yes.


Name of Contractor

Was attached to main

John Bruner & John Deshon

Show by diagram relation of lateral to wall of building served.

3-0 feet from South
East corner the
Main Building
7-0. Depth.



Signed

John Deshon

Inspector for City

Filed at Engineer's Office

OCT 15 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2008

PERMIT TO TAP SEWER

Massillon, O., Oct 13th 1905

Received of Jess Brunker fee of \$ 2.00

for which permission is granted John H. Cherkwood

to tap Sanitary sewer, on the side

of West Cherry Ave., the premises being Lot. No. 1462
St.

House No. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Jess Brunker