## Nº 2009

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	A THE REAL PROPERTY.	gale of the second
SOME SE	D	

11 +11 1001					
Date Inspected Oat 16,1925	If so how and location from first manhole down stream  Distance from first manhole				
House No. 1307, 911					
Size of pipe used le inch	down stream to ditch at curb line and depth 125-3. from Man Hole Porth 6-6. Deep				
Was lateral at curb?	The second of th				
Was attached to main	Name of Contractor				
Show by diagram relation of lateral to					
3-0. feet from	v South.				
3-0. feit furn Det E	asour the				
main	Building				
5-10-6	Beilding.				
· · · · · · · · · · · · · · · · · · ·	CGT 1 5 1925				
Signed Im Westra	Filed at Engineer's Ottice				
Inspector for Cit	y and the second of the second				
Domartes					

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

**Nº** 2009

## PERMIT TO TAP SEWER

	•	\$4 \$4	Ma	ssillon, O.,	e a	15	193.5
Receiv	ved of	1m	Finder		fee o	of \$ 2 -4	<b>2</b>
or wh <b>ich pe</b>	rmission is	granted	Frank	Rudt			<u>:</u>
o tap	hout		sewer, c	on the	tus		side
of Cu	II		.Av St.	e, the premis	es being Lot.	No. 17	८०
House No.	pa1	911 Work to	be done in acco	ordance with (	Ordinance No	. 2323, duly	passed
by the City (	Council, an	d Rules of th	e Department o	f Public Servi	ice.		
Name of Co	ntractor	10 m	7 mln	**************************************			