

Nº 2011

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Date Inspected Oct. 22, 1925

House No. 1316

Size of pipe used 6 inch

Was lateral at curb? yes.

Was attached to main


If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth 29-10. from Man Hole West. 5-0. Deep.

Name of Contractor Jose Brunke & John Deshou

Show by diagram relation of lateral to wall of building served.

Corner South West
Main Building
6-6. Deep.



Signed Am. Deshou
Inspector for City

Filed at Engineer's Office

OCT 27 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2011

PERMIT TO TAP SEWER

Massillon, O.,

Oct 15th 1925

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor