

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

2-14

Nº 2012

Date Inspected Oct. 16 1925

House No. Ltr B. 772.

Size of pipe used 4 inch

Was lateral at curb? yes.

Was attached to main

If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth 353-0 from Man Hole on Hayes Road. 2-6. Depth


Name of Contractor Jesse Brunner & John Nesbore

Show by diagram relation of lateral to wall of building served.

2-0 from south east
corner the porch. 2-6 Depth

2-0 from North West
corner the Building

2-6 Depth



OCT 22 1925

Signed John Nesbore
Inspector for City

Filed at Engineer's Office

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2012

PERMIT TO TAP SEWER

Massillon, O., Oct 15th 1915

Received of Brounke - Darden fee of \$ 2.00

for which permission is granted Mr. Miller

to tap Sanitary sewer, on the North side

of North Ave., the premises being Lot. No. 2834
237 St.

House No. 1018. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Brounke - Darden