



FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2014

Date Inspected Oct. 20, 1925

House No. Lot 42, 2218 824

Size of pipe used 6 inch

Was lateral at curb? Yes.

Was attached to main


Show by diagram relation of lateral to wall of building served.

2-0 from south
west corner.
Main Building
6-0. Deep.

If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth 113-6. from Manhole. Dist. 6-0. Deep

Name of Contractor Chas. Street



Signed Mr. Dechow
Inspector for City

Filed at Engineer's Office

OCT 22 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2014

PERMIT TO TAP SEWER

Massillon, O., Oct 15th 1925

Received of Chas. Standa fee of \$ 2.00

for which permission is granted Mr. Lipp

to tap Sanitary sewer, on the North side
of Sheffield Ave., the premises being Lot. No. 3974
2215
St.

House No. 824. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Chas. Standa