No

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

- 53

Date Inspected Val [] 1 / 9)	If so how and location from first manhole down stream				
House No. 2015 Size of pipe used 6 mol	Distance from first manhole down stream to ditch at curb line and depth 36-7. Some Man Hole South 5-6. Deep				
Was lateral at curb? Yes, Was attached to main	Name of Contractor Dominick Dissor				
Show by diagram relation of lateral to	wall of building served.				
2-ofut from Ofreth Greek posses spills 6-10. Dufe	Rosel.				
Signed Inspector for Cit	Filed at Engineer's Office				

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2015

PERMIT TO TAP SEWER

	Massillon, O.,	<u> </u>	111		_19
Received of			_fee of \$		C.O
or which permission is granted Janua	a His		•		
or which permission is granted		1 1- Hart End			
o tapsewe	er, on the	1/20	and Land		side
f 13th ST SE	Ave., the pren	nises being	Lot. No.	2247	
13611 81 81	St.				
House No. 2015. Work to be done in a	ccordance wit	h Ordinanc	e No. 2323	3, duly	passed
y the City Council, and Rules of the Departmen	ıt of Public Se	rvice.			
Name of Contractor Abuseance Co	1277 J. M.				