

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2019

Date Inspected Oct. 21. 1925

House No. Lot 43. 3731

Size of pipe used 4 inch

Was lateral at curb? yes.

Was attached to main _____


Show by diagram relation of lateral to wall of building served.

12 inches from North
corner Main Building
6 - 6' depth.

If so how and location from
first manhole down stream _____

Distance from first manhole
down stream to ditch at
curb line and depth 12 - 6' from Main Bldg. to West
side of street

Name of Contractor Chas. Stuart



Signed Wm. D. Deshan
Inspector for City

Filed at Engineer's Office OCT 22 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2019

PERMIT TO TAP SEWER

Massillon, O., Oct 20th 1925

Received of Chas. Starnes fee of \$ 2.00

for which permission is granted Linder & Smith

to tap Saint Mary sewer, on the south side

of Yale Ave., the premises being Lot. No. 7390 3731
St.

House No. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Chas. Starnes