Nº 2020

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

The state of the s	
Date Inspected Date 2 Vil 92	If so how and location from 13-8. Com Market Gulffell 5-6
House No. 21 137 32	Distance from first manhole
Size of pipe used 4 inch	down stream to ditch at curb line and depth 82-2 4m mm hale flat 5-3.
Was lateral at curb?	Name of Contractor Andrew Marie Contractor
Was attached to main And	Ivalité d'i Contractor
Show by diagram relation of lateral to	wall of building served.
the Building	Marine Care
the Building	
6 - 6 · Walfs	
Signed Um. Weshow	Filed at Engineer's Office
Inspector for Cit	
D 1	



OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2020

PERMIT TO TAP SEWER

Massillon, O.,	19 🐇
Received of	fee of \$ 2
for which permission is granted to de + Marth	
to tap sewer, on the sewer,	
of Ave., the premises bei	ng Lot. No.
House No	ance No. 2323, duly passed
by the City Council, and Rules of the Department of Public Service.	
Name of Contractor	The control of the co