## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N	Ō	2	N	22	
- T	•	~	v	~	

	The second
Date Inspected Dela 27, 1925 If so how and location from	
House No. Late of 1034 Sirst manhole down stream  Distance from first manhole	
House No. Distance from first manhole	
Size of pipe used from down stream to ditch at curb line and depth 114-0, from More Roll, 1/-	6. Deef.
Was lateral at curb? At A. D. A. D. A. D. A. D.	. a A
Was attached to main Name of Contractor	3/2/2011
Show by diagram relation of lateral to wall of building served.	
1-6. from Worth Gast earner Main Building	
corner Main	
Building	
7-0. Week.	
	•
Signed Filed at Engineer's Office	
Inspector for City	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2022

Name of Contractor...

## PERMIT TO TAP SEWER

	Massillon, O., 1923
1	Received of # W Gilta fee of \$2
	for which permission is granted # W All
0	to tap sewer, on the lost side
1	of Jacob Run Paren, the premises being Lat No.
	House No. Work to be done in accordance with Ordinance No. 2323, duly passed
	by the City Council, and Rules of the Department of Public Service.