

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2028

Date Inspected _____

If so how and location from
first manhole down stream _____

House No. 2666 _____

Distance from first manhole
down stream to ditch at
curb line and depth _____

Size of pipe used _____

Was lateral at curb? _____

Name of Contractor _____


Was attached to main _____

Show by diagram relation of lateral to wall of building served.

2-6.4 ft. from 1st floor

Front of house

Garage



Signed _____

Inspector for City

Filed at Engineer's Office

OCT 30 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

3
N^o 2028

Massillon, O.,

Oct. 26 1927

Received of

Wm. Fisher

fee of \$

2.00

for which permission is granted

R.O. Peugner

to tap

sanitary

sewer, on the

north

side

of

W. Tremont

Ave., the premises being Lot. No.

pt 29
30

House No.

2676

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Fisher