



FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2029

Date Inspected Oct 27 1925

If so how and location from
first manhole down stream _____

House No. 9250

Distance from first manhole
down stream to ditch at
curb line and depth 5-6 ft from curb line, 6 in. deep


Size of pipe used 6 in.

Was lateral at curb? _____

Name of Contractor Fisher

Was attached to main yes

Show by diagram relation of lateral to wall of building served.



OCT 28 1925

Signed W. H. Brown

Inspector for City

Filed at Engineer's Office

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2029

PERMIT TO TAP SEWER

Massillon, O.,

Oct. 26, 1923

Received of

Mr. Fisher

fee of \$

2.00

for which permission is granted

Ben Thomas

to tap

sanitary

sewer, on the

north

side

of

H. Tremont

Ave., the premises being Lot. No.

Pt 299
300

House No.

7630

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Fisher