2033

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

97 ton 1997					
Date Inspected	If so how and location from first manhole down stream				
House No.	Distance from first manhole				
Size of pipe used 2 1978	down stream to ditch at curb line and depth 2 the line and depth				
Was lateral at curb?					
Was attached to main	Name of Contractor				
Show by diagram relation of lateral to	wall of building served.				
9-0, flore Source					
Approximately and the second of the second o	The state of the s				
Allenda for property					
Signed	Filed at Engineer's Office 0CT 2 9 1925				
Inspector for Cit					
Remarks					

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2033

PERMIT TO TAP SEWER

·		Massillo	on, O.,	0 4 2724	1925
		a. h	Consequences	fee of \$) summer state of the state of
	Version	1 o market	91 1 to		
for which permissi	on is granted		V.		side
to tap	sailary - deli	sewer, on the Ave., t		ing Lot. No.	
House No	. Work to b	St. oe done in accorda	nce with Ordin	ance No. 2323, duly	y passed
	il, and Rules of the		i kanala		
	tor fens O				