Nº 2037

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

3-10

101	
Date Inspected Man, 2,1925	If so how and location from first manhole down stream 1.269-0. from Man How Man How
House No. St. 99. 3549.	Distance from first manhole
Size of pipe used 4 miles	down stream to ditch at curb line and depth 215-0 from Man Hole 1840. 3-9 Nu
Was lateral at curb?	
Was attached to main Africa	Name of Contractor Gasse Munker & John Weshard
Show by diagram relation of lateral to	wall of building served
H-6. from Worth	Must and the second
Building 6-6. De	

Signed Thir Destrout	Piled at Engineer's Office
Inspector for City	Riled at Engineer's Office NOV 1925
Damarla	1100

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2037

PERMIT TO TAP SEWER

		Massillon, O.,	Och 29th 1925
Received	of	Land Land	fee of \$
or wh ich perm i	ssion is granted	Jak Elli	-tt
o tap	santan	✓ sewer, on the	side 7012
f 2	Kindley .	4th ST NEAve., the pres	nises being Lot. No. 3 5 4 9
House No. 91	8 Work	to be done in accordance wit	h Ordinance No. 2323, duly passed
y the City Cou	ncil, and Rules of	the Department of Public Se	ervice.
on 20 months	ector P	Jan Jan Dender	