FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2040

Date Inspected Dell 30,1925	If so how and location from first manhole down stream
House No. Lat 98, 3310 Size of pipe used & inste	Distance from first manhole down stream to ditch at curb line and depth 199-9 from West Butto Line
Was lateral at curb?	Name of Contractor Chas Strout
Show by diagram relation of lateral to	wall of building served.
in Orther South Mi	
the Duilding	
4-0. Dufe	
Signed Ohn Deshow	
Inspector for Cit	
Remarks	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2040 PERMIT TO TAP SEWER

	and the state of t	ode in operiod Ngjerje siktor	Massillon, O.,	CJ	30	19
Received	d of Cha	Strand			ee of \$ 2	61
for which pern	nission is granted	e en on hand				
to tap	landay	sew.	er, on the	huts	<u> </u>	side
of he	ull'		Ave., the pren	nises being L	ot. No. 3 3) O	<u>}</u>
House No.	. Wo	rk to be done in		h Ordinance	No. 2323, duly	passed
by the City Co	ouncil, and Rules	of the Departme	ent of Public Se	rvice.		•
selli 0 shoot Name of Cont	ractor Obe	- Dtrond		en e	en e	e de la composición