

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

**Nº 2041**

Date Inspected Nov. 3, 1925

House No. 1009 807

Size of pipe used 6 inch

Was lateral at curb? yes

Was attached to main \_\_\_\_\_


Show by diagram relation of lateral to wall of building served.

If so how and location from first manhole down stream \_\_\_\_\_

Distance from first manhole down stream to ditch at curb line and depth 4.6 - 2. from Man. Hole 1st. 6 - 0. depth

Name of Contractor A. Culpin

2 - 0. from Borth's  
Must cover  
the fresh pipe.  
6 - 6. depth



Signed Wm. Dechow  
Inspector for City

Filed at Engineer's Office \_\_\_\_\_

NOV 4 - 1925

Remarks \_\_\_\_\_

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2041

PERMIT TO TAP SEWER

Massillon, O.,

Nov 2 1925

Received of

Nick Linckenhely

fee of \$

2.00

for which permission is granted

Nick Linckenhely

to tap

San

sewer, on the

South

side

of

W Cherry  
807

~~Ave.~~ St.

the premises being Lot. No.

PT 44  
9742

House No.

1009

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Cupio