## Nº 2043

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected DAta H 1995	If so how and location from 1.207-0. from Man Hole Hest 1-6. He
House No. Astrophys. 3503.  Size of pipe used 4 in the	Distance from first manhole down stream to ditch at curb line and depth 202 or from Mane Hole Mast 1-0. Dufe
Was lateral at curb? Was attached to main A & A	Name of Contractor Gesse Brender & John Meshow
Charabar diagram relation of lateral to	wall of building served.
2-4- front so	town the state of
4000 10 1	
Signed Thulleshow	Filed at Engineer's Office
Inspector for Ci	t <b>y</b> magazatan kenggalan di siliku kenalah kenalah kenalah bilangan berajak berajak berajak berajak berajak beraj Bilangan penggalangan penggalangan berajak berajak berajak berajak berajak berajak berajak berajak berajak ber
Remarks	



## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

**Nº** 2043

## PERMIT TO TAP SEWER

	Massillon, O.,	19	
Received of	- Delan	fee of \$2	
for which permission is granted	7 Bates		
to tap	sewer, on the	side	
of Oak	Ave., the premises bei	ng Lot. No. 3503	
House No. 1020 Work to be	e done in accordance with Ordina	ance No. 2323, duly passed	,
by the City Council, and Rules of the I	Department of Public Service.		
Name of Contractor	· Dadwan		