

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2044

Date Inspected Nov. 10, 1975

House No. _____

Size of pipe used 6"

Was lateral at curb? no


Was attached to main yes

Show by diagram relation of lateral to wall of building served.

If so how and location from first manhole down stream 177' From MH at Arthur St.

Distance from first manhole down stream to ditch at curb line and depth ~~From MH at Arthur St. 177'~~

Name of Contractor Chas. Stroud



Signed [Signature]
Inspector for City

Filed at Engineer's Office Nov. 12, 1975

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2044

PERMIT TO TAP SEWER

Massillon, O., Nov 4 1925

Received of L F Haecher fee of \$ 2⁰⁰

for which permission is granted L F Haecher

to tap Sum sewer, on the North side

of Dwight Ave., the premises being Lot. No. pt 1093
St.

House No. 412 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Stured