

Nº 2045

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED



Date Inspected Apr. 6, 1925

If so how and location from
first manhole down stream _____

House No. 2612

Distance from first manhole
down stream to ditch at
curb line and depth 15'-6" from Manhole. Dist. 5'-6" deep.

Size of pipe used 6 inch


Was lateral at curb? yes

Name of Contractor Wm. Fisher

Was attached to main _____

Show by diagram relation of lateral to wall of building served.

9-0 from south wall
corner the Main
Building
6-4 deep.



Signed Wm. Reshore

Inspector for City

Filed at Engineer's Office 11-7-25

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2045

PERMIT TO TAP SEWER

Massillon, O.,

19²⁵

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor