OLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2049

Date Inspected The House No. 1/5 Size of pipe used 1/2016	If so how and location from first manhole down stream April 9-0 Now Manhole down stream to ditch at curb line and depth
Was lateral at curb?	
Was attached to main Show by diagram relation of lateral to	Name of Contractor wall of building served.

Remarks Signed Filed at Engineer's Office NOV 2 0 1925

Remarks Signed Filed at Engineer's Office NOV 2 0 1925

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2049 PERMIT TO TAP SEWER

	Massillon, O., 19	
	Received of	
Sign Assessment	for which permission is granted Plane	·
Salvence charge in springs received	to tap sewer, on the sid	e
	of Ave., the premises being Lot. No. 300 2	
	House No. // 5 Work to be done in accordance with Ordinance No. 2323, duly pass	<u></u>

by the City Council, and Rules of the Department of Public Service.

a harmony of the

Name of Contractor