

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**


Nº 2053

4-6

Date Inspected Nov. 10, 1925 If so how and location from
House No. Lot. B. 2314 837 first manhole down stream
Size of pipe used 6 inch Distance from first manhole
down stream to ditch at
curb line and depth 120-6 ft from Man Hole East
Was lateral at curb? yes 4-8. Deep
Name of Contractor Chas. J. H. H. H.
Was attached to main _____

Show by diagram relation of lateral to wall of building served.

4-0. ft from North
West corner
The Plaza
6-8. Deep



Signed Mr. J. H. H.
Inspector for City

Filed at Engineer's Office

NOV 12 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No 2053

Massillon, O.,

19.

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No. 4046
St.

House No.

837

Work to be done in accordance with Ordinance No. 2323, duly pr

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Wants insp
1st thing in
morning