

12 ✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2055

Date Inspected Nov 18, 1925

House No. Lot 92, 141

Size of pipe used 6 inch

Was lateral at curb? yes

Was attached to main _____


Show by diagram relation of lateral to wall of building served.

2-0' from south west
corner Main
Building
7-0' Dapt

If so how and location from first manhole down stream _____

Distance from first manhole down stream to ditch at curb line and depth 65-0' from Main N. duct 8-0' deep

Name of Contractor James Brunkert John Bashore



Signed Wm. Bashore
Inspector for City

Filed at Engineer's Office NOV 2 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2055

PERMIT TO TAP SEWER

Massillon, O., Nov 11th 1911

Received of Bunker - Decker fee of \$ 2.00

for which permission is granted Free a License

to tap saint aug sewer, on the north west corner side

of Pigeon Run Rte Ave., the premises being Lot. No. 441
St.

House No. Work to be done in accordance with Ordinance No. 2323, duly pas-

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Bunker - Decker