1

2064

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

10 4000

| Date Inspected Nov. 28- 1926 If so how as first manhol | nd location from e down stream |
|--|---|
| House No. //07 Distance from | om first manhole |
| Size of pipe used 4" down stream curb line an | d depth |
| Was lateral at curb? Name of Co | ontractor John 2 |
| and the control of th | The same against the same against the same and |
| Show by diagram relation of lateral to wall of buildi | ng served. |
| | |
| | |
| | west walnut st |
| eurs y | |
| The second se | |
| | HOUSE = 90. 4" B |
| | HOUSE YB-T-TT-B-T |
| | 11073 4 4 |
| Signed black Olsea | Filed at Engineer's Office |
| Inspector for City | |
| | DEC 1 1 1926 3 6 |
| Remarks | 3 3 |
| | |

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2064 PERMIT TO TAP SEWER

| Massillon, O., | 1 3 |
|---|------|
| Received of | |
| for which permission is granted Office A | |
| to too | |
| ofAve., the premises being Lot. No. | side |
| St. 3 2 6 3 | |
| House No. 1/0 ? Work to be done in accordance with Ordinance No. 2323, duly pas | sed |
| by the City Council and Rules of the Department of Public Samiles | |

Name of Contractor