

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2078

Date Inspected 12/2/25

House No. 1119

Size of pipe used 6"

Was lateral at curb? yes


Was attached to main _____

If so how and location from
first manhole down stream _____

Distance from first manhole
down stream to ditch at
curb line and depth 7'

Name of Contractor Wm. Fisher

Show by diagram relation of lateral to wall of building served.



Signed J. H. Maloney
Inspector for City

Filed at Engineer's Office

DEC 2 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2078

PERMIT TO TAP SEWER

Massillon, O., Mar 20 1920

Not before Wednesday
Received of Wm Fisher

fee of \$ 2.00

for which permission is granted Anthony Corp.

to tap sanitary

sewer, on the South

side

of Medill

Ave., the premises being Lot. No. 2285
St.

House No. 1119

Work to be done in accordance with Ordinance No. 2323, duly passed
by the City Council, and Rules of the Department of Public Service.

Name of Contractor Wm Fisher