

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3-28 ✓

Nº 2080

Date Inspected 12/3/25

House No. New Hse 417

Size of pipe used 6

Was lateral at curb? Yes


Was attached to main _____

If so how and location from
first manhole down stream _____

Distance from first manhole
down stream to ditch at
curb line and depth 217' 4' Deep

Name of Contractor Jess Brunker

Show by diagram relation of lateral to wall of building served.



Signed M. R. Smith
Inspector for City

Filed at Engineer's Office

DEC 3 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2080

PERMIT TO TAP SEWER

Massillon, O., Dec 2 1935

Received of J Brunker fee of \$ 2.00

for which permission is granted Mr Cramer

to tap Sewer sewer, on the West side

of 7 Marshall Hill Ave., the premises being Lot. No. 42 5040
18th ST NW St.

House No. 417. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Brunker & Dasher