

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2081



Date Inspected 12/3/25

If so how and location from
first manhole down stream

House No. 819

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6"

Was lateral at curb? Yes

Name of Contractor J. Wittman

Was attached to main

Show by diagram relation of lateral to wall of building served.



Signed M. R. Smith
Inspector for City

Filed at Engineer's Office

DEC 3 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2081

PERMIT TO TAP SEWER

Massillon, O., Dec 3 1923

Received of J. Wilkman fee of \$ 2

for which permission is granted J. Brilger

to tap San J sewer, on the West side

of Clay Ave., the premises being Lot. No. 2071
St.

House No. 819 Work to be done in accordance with Ordinance No. 2323, duly passed
by the City Council, and Rules of the Department of Public Service.

Name of Contractor Wilkman

about 3 PM