

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2089

Date Inspected Dec 18, 1925

If so how and location from
first manhole down stream

House No. New.

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 4"


Was lateral at curb? Yes and one
pipe in

Name of Contractor

Chas. Stroud

Was attached to main No

Show by diagram relation of lateral to wall of building served.



Signed Clark Elsea
Inspector for City

Filed at Engineer's Office Dec. 18, 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

8:00
N^o 2089

Massillon, O.,

Dec 15th 1925

Received of

Chas. Stanga

fee of \$

for which permission is granted

to tap

sanitary sewer, on the

side

of

Peacock Ave., the premises being Lot. No. 2167-2168 St.

House No. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Chas. Stanga