2099

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected //2 2/26	If so how and location from first manhole down stream
House No. 328 Size of pipe used 4"	Distance from first manhole down stream to ditch at
	curb line and depth
Was lateral at curb?	
Was attached to main	Name of Contractor Charlie 3troud
Show by diagram relation of lateral to	
C.	
	1 11 12 1 V V
Mary Daniel	And the company of the state of the company of the
Signed Clarke Elsen	Filed at Engineer's Office 2/1/26
Inspector for Cit	y
Remarks Old 4" Lolerah was co	needed to a 4" Jansener in Dailer Terrace
as shown above	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2099

PERMIT TO TAP SEWER

		Massillon, O.,	19
Angle of the second sec	er e Sagar Janes III.	P. San	
Received of	of	To the second second	fee of \$
for which permi	ssion is granted	1 de Carante Carante	Bash and the same
	and the		pelangan katalog 💹 💋 katalog 🗀
	V	Ave., the premise	es being Lot. No. 32 8
		St.	
House No		ne in accordance with (Ordinance No. 2323, duly passed
by the City Cou	ncil, and Rules of the Depa	rtment of Public Servi	ce.
Name of Contra	ctor Clas Ita		